

Inspection Photos

API: 011-06174

Operator: CHOLLA PETROLEUM INC

Inspection Date: 6/26/2024

County: Bent



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road. The road has not been reclaimed and the cattlegurd remains.



Inspection Photos



Photo 2. The two track road has not been reclaimed and soils are compacted along the road.



Inspection Photos



Photo 3. Facing southwest toward the location. There area areas of the location that are bare of vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing east at the location. This area has not been reclaimed and has no vegetation.



Inspection Photos



Photo 5. East side of the location facing north. There is an outline of the cut slope which is not revegetated.



Inspection Photos



Photo 6. Facing southwest at the location. This entire are consists of mostly undesirable weeds. It appears there was a drilling in this area from historic imagery.



Inspection Photos



Photo 7. View of vegetation shows undesirable weeds (Russian thistle).



Inspection Photos



Photo 8. South side of the location facing northeast. This entire are consists of mostly undesirable weeds. It appears there was a drilling in this area from historic imagery.

