

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

705000739

FIELD INSPECTION FORM

Loc ID 336380 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206609	WELL	SI	01/30/2024	GW	013-06104	DONIPHAN-SHIELDS 2	PA
289602	WELL	SI	01/24/2024	GW	013-06541	DONIPHAN SHIELDS 12-11	PA
336380	LOCATION	AC			-	DONIPHAN-SHIELDS-61N69W 11NENW	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 206609 Type: WELL API Number: 013-06104 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289602 Type: WELL API Number: 013-06541 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 336380 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Wells are plugged and abandoned (Doniphan Shields 2, 12-11); ECMC form 42 notice of start of plugging operations doc #403788882 received on 05/13/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed. No flowlines and/ or flowline risers observed. Remediation work is in progress.	maclarej	06/27/2024
As outlined on COGCC form 19 spill report Doc #403830548 received on 06/20/2024: During facility decommissioning activities, elevated PID's, hydrocarbon staining, and odor were observed indicating a historical release. The impacted soil will be removed and hauled for disposal. Lease operators are coached to conduct routine AVO inspections at all oil and gas locations.	maclarej	06/27/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000742	PA well markers	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604407
705000743	View of location to east; OOS AST	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604408