

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2024

Submitted Date:

06/27/2024

Document Number:

713900701**FIELD INSPECTION FORM**Loc ID 319519 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| ,            |       | inspections@civiresources.com |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|----------------------|-------------|
| 243603      | WELL     | PA     | 12/05/2015  | GW         | 123-11395 | HIPPEN 1-32          | RI          |
| 319519      | LOCATION | CL     |             |            | -         | HIPPIN-61N68W 32NWNW | RI          |

**General Comment:**

This is a Final Reclamation Inspection for PA Well AP#123-11395 and its associated tank battery. Well was plugged and abandoned 12/05/2015.

|  |      |  |  |                 |  |
|--|------|--|--|-----------------|--|
| Location   |      |  |  |                 |  |
| Overall Good: <input type="checkbox"/>                 |      |  |  |                 |  |
| Emergency Contact Number:                              |      |  |  |                 |  |
| Comment:   |      |  |  |                 |  |
| Corrective Action:                                     |      |  |  | Date: _____     |  |
| Overall Good: <input type="checkbox"/>                 |      |  |  |                 |  |
| <b>Spills:</b>   |      |  |  |                 |  |
| Type   | Area | Volume   |  |                 |  |
| In Containment: No                                     |      |  |  |                 |  |
| Comment:   |      |  |  |                 |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |  |  |                 |  |
| <b>Equipment:</b>                                      |      |  |  |                 |  |
|  |      |  |  | corrective date |  |
| Type:  |      | #  |  |                 |  |
| Comment:   |      | No visual evidence of oil and gas equipment at the well or associated tank battery location. Refer to the attached inspection photos.                                      |  |                 |  |
|  |      | Sprinklers were observed at the tank battery location. After contacting an Operator representative they were identified as sprinklers used by the neighboring golf course. |  |                 |  |
| Corrective Action:                                     |      |  |  | Date:           |  |
| <b>Venting:</b>  |      |  |  |                 |  |
| Yes/No   |      |  |  |                 |  |
| Comment:   |      |  |  |                 |  |
| Corrective Action:                                     |      |  |  | Date:           |  |
| <b>Flaring:</b>  |      |  |  |                 |  |
| Type   |      |  |  |                 |  |
| Comment:   |      |  |  |                 |  |
| Corrective Action:                                     |      |  |  | Date:           |  |



**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% Pass Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: [The well location \(Location ID 319519 with API 123-11395\) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and tank battery appear reflective of reference areas.](#)

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

|                           |      |                                 |                          |                     |                          |
|---------------------------|------|---------------------------------|--------------------------|---------------------|--------------------------|
| Overall Final Reclamation | Pass | Well Release on Active Location | <input type="checkbox"/> | Multi-Well Location | <input type="checkbox"/> |
|---------------------------|------|---------------------------------|--------------------------|---------------------|--------------------------|

Storm Water:

|   |                 |                         |                       |               |                          |                   |
|---|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------------|
| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment           |
|   |                 |                         |                       |               |                          |                   |
| <div>Comment: <div>At the time of this inspection, no stormwater erosion issues were observed at the location or along the access road.</div></div> |                 |                         |                       |               |                          |                   |
| Corrective Action: <div></div>  |                 |                         |                       |               |                          | Date: <div></div> |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT   |                 |                         |                       |               |                          |                   |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                   |   |
|--------------|-------------------|---|
| Document Num | Description       | URL   |
| 713900709    | Inspection photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604985">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604985</a> |