

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225

Jun 26, 2024 at 12:20:20 PM
39.956535,-103.929290
ECMC



Pic 1 weeds unmanaged on lease road

Jun 26, 2024 at 12:27:58 PM
39.955152,-103.934972
ECMC



Pic 2 tank placard is inadequate/ weeds unmanaged

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225

Jun 26, 2024 at 12:28:09 PM
39.955152,-103.934972
ECMC



Pic 3 sign is inadequate

Jun 26, 2024 at 12:28:56 PM
39.955230,-103.935042
ECMC




Pic 4 risers on location are not LOTO

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 5 Risers are not LOTO



Pic 6 Wellhead sign is inadequate

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 7 stormwater damage on south end of location



Pic 8 Anchors are not marked correctly, needs to be highly visible.

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 9 stormwater damage on south end of location

Pic 10 stormwater damage on south end of location

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 11 Pit has been filled, no form 27 on file



Pic 12 Pit has been filled no form 27 on file

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 13 riser is lot LOTO