

**Inspection Photos**  
**Location Name: Linnebur 4**  
**Location ID: 319762**



**Pic 1 wellhead / pumpjack**



**Pic 2 Stained soil was covered by dirt, red arrow shows where dirt was shoveled to cover contaminated soil by wellhead.**

**Inspection Photos**  
**Location Name: Linnebur 4**  
**Location ID: 319762**



**Pic 3 wellhead sign is inadequate**



**Pic 4 lock on fencing**

**Inspection Photos**  
**Location Name: Linnebur 4**  
**Location ID: 319762**



**Pic 5 motor house**



**Pic 6 contaminated soil covered with other dirt to cover contaminated soil.**

**Inspection Photos**  
**Location Name: Linnebur 4**  
**Location ID: 319762**

Jun 26, 2024 at 1:11:13 PM  
39.962222,-103.935577  
ECMC



**Pic 7 deadmen are not properly marked**

Jun 26, 2024 at 1:13:14 PM  
39.962685,-103.936895  
ECMC



**Pic 8 Riser is not LOTO**

**Inspection Photos**  
**Location Name: Linnebur 4**  
**Location ID: 319762**