

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2024

Submitted Date:

06/24/2024

Document Number:

709401027

**FIELD INSPECTION FORM**

Loc ID 319929 Inspector Name: WOLD, REED On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10711  
Name of Operator: PAINTED PEGASUS PETROLEUM LLC  
Address: 16820 BARKER SPRINGS RD #521  
City: HOUSTON State: TX Zip: 77084

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Conklin, Curtis		curtis.conklin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201916	WELL	PR	08/01/2021	GW	001-07320	UPRR 23 PAN AM L 1 (OWP)	RI
319929	LOCATION	AC			-	UPRR 23 PAN AM L-62S64W 9CNE (OWP)	RI

**General Comment:**

This is an orphaned well inspection with emphasis on stormwater controls and reclamation status. Inspection to evaluate surface conditions only. As the well is part of Orphaned Well Program all other open/required tasks for well/location abandonment remain open until completed and closed.

With no current operator corrective actions from previous field inspections have not been performed. Previous corrective actions will be evaluated and may be converted into well abandonment task. Tasks will be prioritized and completed as part of well abandonment. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable photo log.

**Inspected Facilities**

Facility ID: 201916 Type: WELL API Number: 001-07320 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 319929 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709401028	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606508">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606508</a>