

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2024

Submitted Date:

06/27/2024

Document Number:

709401050

**FIELD INSPECTION FORM**

Loc ID: 320044 Inspector Name: WOLD, REED On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 10711  
Name of Operator: PAINTED PEGASUS PETROLEUM LLC  
Address: 16820 BARKER SPRINGS RD #521  
City: HOUSTON State: TX Zip: 77084

**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michaelhickey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202365	WELL	SI	06/01/2020	OW	001-07770	CARLSON 42-33 1 (OWP)	SI
320044	LOCATION	AC			-	CARLSON 42-33-62S64W 33SENE (OWP)	RI

**General Comment:**

This is an orphaned well inspection with emphasis on stormwater controls and reclamation status. Inspection to evaluate surface conditions only. As the well is part of Orphaned Well Program all other open/required tasks for well/location abandonment remain open until completed and closed.

With no current operator corrective actions from previous field inspections have not been performed. Previous corrective actions will be evaluated and may be converted into well abandonment task. Tasks will be prioritized and completed as part of well abandonment. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable photo log.

**Inspected Facilities**

Facility ID: 202365 Type: WELL API Number: 001-07770 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 320044 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709401051	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606519">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606519</a>