

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2024

Submitted Date:

06/27/2024

Document Number:

709401054

FIELD INSPECTION FORM

Loc ID 320365 Inspector Name: WOLD, REED On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 10711
Name of Operator: PAINTED PEGASUS PETROLEUM LLC
Address: 16820 BARKER SPRINGS RD #521
City: HOUSTON State: TX Zip: 77084

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203552	WELL	SI	12/01/2019	GW	001-09112	HELIX 1 (OWP)	RI
485158	TANK BATTERY	SI	09/27/2023		-	HELIX-62S64W 30NWNW	RI

General Comment:

This is an orphaned well inspection with emphasis on stormwater controls and reclamation status. Inspection to evaluate surface conditions only As the well is part of Orphaned Well Program all other open/required tasks for well/location abandonment remain open until completed and closed.

With no current operator corrective actions from previous field inspections have not been performed. Previous corrective actions will be evaluated and may be converted into well abandonment task. Tasks will be prioritized and completed as part of well abandonment. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable photo log.

Inspected Facilities

Facility ID: 203552 Type: WELL API Number: 001-09112 Status: SI Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485158 Type: TANK API Number: - Status: SI Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709401055	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606521