

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2024

Submitted Date:

06/27/2024

Document Number:

709401056

FIELD INSPECTION FORMLoc ID 319932 Inspector Name: WOLD, REED On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michaelhickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201928	WELL	PR	06/01/2020	GW	001-07332	CHAMPLIN 75 AMOCO J 1 (OWP)	RI
319932	LOCATION	AC			-	CHAMPLIN 75 AMOCO J-62S65W 25SWNE (OWP)	RI

General Comment:

This is an orphaned well inspection with emphasis on stormwater controls and reclamation status. Inspection to evaluate surface conditions only. As the well is part of Orphaned Well Program all other open/required tasks for well/location abandonment remain open until completed and closed.

With no current operator corrective actions from previous field inspections have not been performed. Previous corrective actions will be evaluated and may be converted into well abandonment task. Tasks will be prioritized and completed as part of well abandonment. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

See link at end of report for path to downloadable photo log.

Inspected Facilities				
Facility ID: 201928	Type: WELL	API Number: 001-07332	Status: PR	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 319932	Type: LOCATION	API Number: -	Status: AC	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709401059	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606522