

Inspection Photos

06/25/2024

Operator: ENERGY INVESTMENTS INC - 10469

Location ID: 316782

Inspection Doc: 696205929

Routt County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from northwest, north, east, to southeast.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782




Photo 3: Photos 3-5 taken from the wellhead. Photo shows stained soils / impacts due to a leak at the wellhead.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 5 See comments under photo 3. Fluids appear to be actively leaking from well and stuffing box.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 6: Photos taken from the well. Photo left shows fluids within the secondary containment measure. Photo also shows wildlife protection measures are missing from the containment BMP. Photo right shows additional soil staining around the well.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 7: Fluids leaking from motor of the pump jack, resulting in stained soils.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 8: Container label adjacent to well is no longer legible.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 9: Photos taken from the tank battery facility on the north end of the Location. Photo left shows signage has not been posted at the battery facility. Photo right shows signage at the crude oil tank has not been maintained.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 10: Tanks at battery facility missing Operator emergency contact number.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 11: Photos 11-13 taken from the tank battery facility on the north end of the Location. Photos shows fluids/spills within containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 12: See comments under photo 11. Photo right also shows stained soils next to battery facility.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 13: See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 14: Photos right shows wildlife mortality within the tank battery facility containment. Photo right shows an open barrel containing unknown fluids. Wildlife protection measures missing or insufficient.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 15: Unused tank with crack observed stored at the battery facility. Tank requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 16: Labels at container no longer legible.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 17: Photos 17-20 provide examples showing various trash, debris and/or unused equipment improperly stored on the Location. Photo left taken from the propane tank next to the wellhead. Photo right taken from the northwest end of the Location, facing southeast.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 18: See comments under photo 17. Photos taken from the northwest end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 19: See comments under photo 17. Photos taken from behind the housing unit on the northwest end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 20: See comments under photo 17. Photo left taken from next to wellhead. Photo right shows unused propane tank stored on the southwest end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 21: Photos show unlabeled barrels improperly stored on the Location. BMPs to prevent and/or to contain a spill or release are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 22: Photos examples of Noxious Weeds (Bull thistle, Houndstongue) observed on the production and interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 23: Photos taken from the north and of the Location, east of the battery. Photo shows open pipe. BMPs to prevent wildlife access missing.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 24: Photos 24-29 taken from the “Wolf Mountain Tank Battery Facility (#449642)”, Located on the north end of Beeman O&G’s Routt Bonanza-67N87W/22SENE Location (#316756). Photo left shows API information remains missing at the battery signage. Photo right shows tanks at the facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 25: Photos shows that secondary containment measure remains in disrepair- containment is not impervious to contain a spill or release.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 26: Photos show fluids remain in the honeypot. Photo also shows spills remaining around the loadline.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 27: Photos show signage at the tank do not comport with 605 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782



Photo 28: Photos examples showing covers at 3 of the 4 tanks on the Location have not been replaced. Photos also show stained soils due to spills at the battery facility have not been cleaned.

Inspection Photos

Operator Name: ENERGY INVESTMENTS INC - 10469

Location ID: 316782




Photo 30: Photos examples show additional spills/stained soils that have not been cleaned/removed at the battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources