

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/30/2024

Document Number:

715200432**FIELD INSPECTION FORM**Loc ID 321824 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| OBryhim, Reesa | | ROBryhim@mulldrilling.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 208129 | WELL | PR | 02/25/2020 | OW | 017-07064 | NW ARAPAHOE UNIT (NWAU) 6 | PR |

General Comment:[Routine Inspection](#)

Location

| | | | |
|--------------------|--------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Elevated gravel road through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Sticker on chemical drum | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit, wellhead, VGS and compressor | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Compressor | # 1 | | |
| Comment: | Skid mounted booster compressor | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | VGS on south side of wellhead | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 4 | | |
| Comment: | Electric panel, cathodic rectifier and 2-chemical drums w/containment | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|---------------|--|-------|
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | Fairfield 228 | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|--|--|-------|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 208129 | Type: | WELL | API Number: | 017-07064 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Central tank battery for (NWAU 2, 3, 4, 5, 6 & 38) 2790' NNW @ 38.901960/-102.183830 | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | Material Handling And Spill Prevention | Pass | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|----------------|---|
| Document Num | Description | URL |
| 715200446 | location photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607256 |