

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 14C-20-692 Pad

Location # 335300



Photo # 1699 From entrance to location



Photo # 1700 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 14C-20-692 Pad

Location # 335300



Photo # 1701 Location



Photo # 1702 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 14C-20-692 Pad

Location # 335300



Photo # 1703 Location



Photo # 1704 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 14C-20-692 Pad

Location # 335300



Photo # 1705 Open ended load line



Photo # 1706 Tank containment damaged/buckling

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 14C-20-692 Pad

Location # 335300



Photo # 1707 Tank containment damaged/buckling



Photo # 1708 Tank containment damaged/buckling

Inspection Photos

Location Name: TEP Rocky Mountain LLC BRYNILDSON 14C-20-692 Pad

Location # 335300



Photo # 1709 Tank containment damaged/buckling