

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2024

Submitted Date:

06/30/2024

Document Number:

708904137

FIELD INSPECTION FORM

Loc ID 334874 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

27 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211528	WELL	PR	03/12/2001	GW	045-07288	BERNKLAU RMV #110-33	PR
263045	WELL	PR	10/10/2002	GW	045-08099	BERNKLAU RWF 343-33	PR
263046	WELL	PR	04/01/2014	GW	045-08100	BERNKLAU RWF 344-33	PR
263047	WELL	PR	10/08/2002	GW	045-08101	BERNKLAU RWF 334-33	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 06/27/2024 at approximately 13:18 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 110-33 Pad. Location # 334874 in Garfield County Colorado.
Please refer to inspection 708901948 conducted on 10/12/2023, previous corrective actions have been completed. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.

This is a summary of inspection report.

[Split pad/Remote location - Shared facilities with the BERNKLAU RMV 106-33 pad, location # 324055](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Production tank label weathered & starting to become illegible - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign weathered & cracking but still legible at this time		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank Chemical tank label starting to peel & some required info is not visible - please refer to photo log		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		

Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Chemical tank & Flameless gas infrared catalytic heater - hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	RWF 343-33 well bradenhead has pressure transducer & Taylor plug located on bradenhead, bradenhead valve is accessible. Remaining 3 wells have Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		
Comment:	Marked 2 deadman in close proximity are marked with only 1 marker		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:	Tank equipped with telemetry				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211528 Type: WELL API Number: 045-07288 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 263045 Type: WELL API Number: 045-08099 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:	Shut In	
Corrective Action:		Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 263046 Type: WELL API Number: 045-08100 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 263047 Type: WELL API Number: 045-08101 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						Sparse to none in most areas
Compaction						Light compaction in some areas
		Compaction				
Check Dams						May need maintenance in the near future
		Gravel				Sparse to none
		Culverts				
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containment

Comment: Check dams in ditch are showing signs of erosion & may need maintenance in the near future. (East side of location)

Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker, Equipment & Stormwater for comments	smelserw	06/30/2024
Split pad/Remote location - Shared facilities with the BERNKLAU RMV 106-33 pad, location # 324055		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904138	Inspection 708904137 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607502
708904139	Inspection 708904137 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607503