

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2024

Submitted Date:

06/24/2024

Document Number:

698602130

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
399613 _____ St John, William (Cal) _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 710 _____
Name of Operator: AEON ENERGY CORP _____
Address: 2600 SOUTH LEWIS WAY #102 _____
City: _____ LAKEWOOD _____ State: _____ CO _____ Zip: _____ 80227 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 17 _____ Number of Comments
3 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Engineering		dnr_ecmc_engineering@state.co.us	
Snyder, Barry	303-922-0590	aeonco@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232914	WELL	PR	02/01/2023	GW	115-05045	PRATT 1R	PR

General Comment:

Routine inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted at oil and gas location.		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 07/08/2024
Type	BATTERY		
Comment:	Well lease sign posted at remote gas meter run.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	No sign or label not posted on tank. No Content/Quantity/Hazard sign at tank.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 07/08/2024
Emergency Contact Number:			
Comment:	Emergency contact information posted on remote meter shed.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation growing around surface equipment at wellhead.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing at wellhead. Fencing is there but currently not assembled.		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Steel separator shed. Door has broken off and laying on ground at well location.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve closed.		

Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	Located at well location.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on access to HV Ranch 32-1. Gas Meter Run. Chart in Meter Box dated 6-1-24. Meter Calibration/Test Log dated 6-29-23. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible at surface.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	07/08/2024
Type: Other	# 1		
Comment:	Remote gas meter shed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:	Tank located at remote metering location and appears to be associated with the HV Ranch CO 34-1 and Pratt 1R well. No signs or labels on tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232914 Type: WELL API Number: 115-05045 Status: PR Insp. Status: PR

Producing Well

Comment: Tubing in wellbore. Tubing valve open. Casing valve closed. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 4/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403834411	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599618
698602139	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599613