

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2024

Submitted Date:

06/24/2024

Document Number:

707800967

**FIELD INSPECTION FORM**Loc ID 413754 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Fulcrum		inspections@fulcrumeo.com	
Penner, annalee		annalee@fulcrumef.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446421	WELL	SO	10/01/2022	OW	057-06557	Marr 0780 10-6H31	SO

**General Comment:****ECMC Inspection Report Summary**

On Tuesday 6/17/2024, I, Inspector Scott Ramsey, witnessed a MIT at Marr 0780 10-6H31, at API # 057-06557 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed MIT on surface casing. MIT passed. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Well signage is incorrect and did not match with ECMC data base.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	1. Well signage is incorrect and did not match with ECMC data base.			
Corrective Action:	Provide proper signage			Date: 07/29/2024
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date: <input type="text"/>
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date: <input type="text"/>

Inspected Facilities

Facility ID: 446421

Type: WELL

API Number: 057-06557

Status: SO

Insp. Status: SO

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: MIT done to maintain status

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403833712	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6598981">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6598981</a>