

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2024

Submitted Date:

06/24/2024

Document Number:

713400167

## FIELD INSPECTION FORM

Loc ID 324465 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

## Operator Information:

ECMC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

## Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

10 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

Contact Name	Phone	Email	Comment
Energy, Gunnison		geops@oxbow.com	
Toews, Wesley		wtoews@blm.gov	

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211701	WELL	PR	09/01/2023	GW	051-06023	FEDERAL 16-4	PR

## General Comment:

## CECMC Inspection Report Summary

On 6/20/2024 at approximately 12:22, Compliance Inspector Dusty Popejoy conducted an on-site inspection at GUNNISON ENERGY LLC FEDERAL-610S90W/16SESE at Location ID #324465 in Gunnison County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area. During the inspection, the following compliance issues were observed:

- 1) Equipment/Meter run - Open entry to wildlife on door/window broken glass, refer to photos with a CA date of 7/4/2024
- 2) Chemical tank - Label is not legible and needs replaced, refer to photos with a CA date of 7/4/2024
- 3) Equipment - Unused/Rig equipment, refer to photos with a CA date of 7/24/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:	970-874-7697 or 911	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Tubing by separator and marker by deadman		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Chemical tank - Label is not legible and needs replaced, refer to photos		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		Date: 07/04/2024
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Marker on southeast side of location fell over		
Corrective Action:			Date:
Type: Other	#		
Comment:	Unused/Rig equipment, refer to photos		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.		Date: 07/24/2024
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:	Open entry to wildlife on door/window broken glass, refer to photos	
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.	Date: 07/04/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	No telemetry					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 211701	Type: WELL	API Number: 051-06023	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Ditches				
Seeding						
Tracking Pad						
Berms		Culverts				
Ditches						
Sediment Traps						
Gravel						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403834343	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599541">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599541</a>
713400168	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599532">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599532</a>