

Interim Reclamation and Stormwater Inspection

June 13, 2024

Operator: GULF EXPLORATION LLC - #10728

Location ID: 456859

Inspection Document #: 697505362

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Little Black Powder #2
Location ID: 456859



Photo 1. Photo taken from the location illustrating the Operator signage.



Photo 2. Photo taken from the entrance of location, facing North. Photo illustrates the access road that remains, which has an approved Commission variance.

Note- much of the vegetation growing along the access road BMP area and interim area is Cereal rye, which is not reflective of reference area vegetative conditions.



Inspection Photos
Location Name: Little Black Powder #2
Location ID: 456859



Photo 3. Photo taken from the eastern interim area, facing East. Photo illustrates the interim area is dominated by Cereal rye, which is not reflective of reference area vegetative conditions.



Photo 4. Photo taken from the eastern interim area, facing North. See comments under Photo 3.



Inspection Photos
Location Name: Little Black Powder #2
Location ID: 456859



Photo 5. Photo taken from the northeastern interim area, facing Northeast. See comments under Photo 3.



Photo 6. Photo taken from the northern interim area, facing East. See comments under Photo 5.

Note- there are other grass species observed within portions of the northern interim area but are introduced plant species like Smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 697505362

Inspection Photos
Location Name: Little Black Powder #2
Location ID: 456859



Photo 7. Photo taken from the northern interim area, facing North. Photo illustrates bare patches with no vegetation establishment.

Inspection Photos
Location Name: Little Black Powder #2
Location ID: 456859



Photo 8. Photo taken from another portion of the northern interim area, facing North. See comments under Photo 7.