

Inspection Photos

June 25th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 325118

Inspection Document #: 714000892

La Plata County, CO

Township: NSWE 21 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118

6/25/24
+37.087376,-107.719205
73° E



6/25/24
+37.087376,-107.719205
69° E

Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118



Photo 2. Erosion issues persist in the southern cut slope area. Storm water BMP wattles needs maintenance.

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118

6/25/24
+37.087376,-107.719205
106° E



Photo 3. Berm/secondary containment corrective action identified in the previous inspection doc #693903535 has been addressed/resolved.

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118



Photo 4. View of storm water BMPs that remain functional in the northern interim reclamation area.

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118



Photo 5. View of the western interim reclamation area facing southwest.



Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118



Photo 6. View of the reference are comprised of smooth brome, sage brush and juniper.

