

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



1. View of wellhead. Note vegetation growing across location.



2. Tubing pressure at time of inspection.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



3. Casing pressure at time of inspection.



4. View of Tank Battery. Note rust streak down tank on the left.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



5. Close up of hole in wall of left side 400 BBL tank.



6. Additional view of rusting, holes, and pitting on the backside of the left tanks wall.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



7. View of 200 BBL Tank. No Content/Quantity/Hazard lable on tank. Note vegetation.



8. Steel Injection Pump and Equipment Building. Note berm has been opened up on left side front of building.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



9. View of Filter Pots inside building.



10. Equipment, debris, and trash inside pump building.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



11. Dumped trash pile on location.



12. Unused Tanks on location.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



13. Rods and polish rod dumped on location.



14. Loose wire on location. Creates a wildlife and live stock hazard.

Inspection Photos
Location Name: Mailander SWD 16B-34-6-45
API Number: 095-06149



15. Location overview from wellhead looking towards Tank Battery. Note vegetation.



16. Location overview from entry point looking towards Tank Battery.