

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2024

Submitted Date:

06/25/2024

Document Number:

696306461

FIELD INSPECTION FORM

Loc ID 435681 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435682	WELL	PR	04/23/2014	OW	123-38733	Antelope K21-O24-15HNB	PR
435683	WELL	PR	08/01/2023	OW	123-38734	Antelope 31-34-15HNB	PR
435684	WELL	PR	02/01/2024	OW	123-38735	Antelope K-O-15HNB	PR
435685	WELL	PR	04/23/2014	OW	123-38736	Antelope K31-O34-15HNB	PR

General Comment:

This is a Follow-Up Inspection to FIR 696305512 dated 12.14.2023

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	MT-56 Container STILL Missing Label; see photos Same Corrective Action Date remains		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	01/15/2024

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 435682 Type: WELL API Number: 123-38733 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435683 Type: WELL API Number: 123-38734 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435684 Type: WELL API Number: 123-38735 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435685 Type: WELL API Number: 123-38736 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Inspection. MT-56 STILL missing adequate Labeling	petrie	06/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403835222	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6600485
696306462	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6600481