

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2024

Submitted Date:

06/25/2024

Document Number:

715200413**FIELD INSPECTION FORM**Loc ID 320972 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kelly, George		envexbaca@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205623	WELL	PR	04/01/2023	GW	009-06034	COPE, NELLIE 1-16	PR

**General Comment:**[Routine Inspection](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Dirt and gravel road through farm ground			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Sticker and stencil on water tank. NFPA label needs replaced			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 07/24/2024
Type	WELLHEAD			
Comment:	Lease sign mounted to meter shed			
Corrective Action:	Sign is not legible. Install sign to comply with Rule 605.d.			Date: 07/24/2024
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	VGS on east side of water tank and unused tubing on west side			
Corrective Action:	Comply with Rule 606			Date: 07/24/2024
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Wire panels around unit and wellhead			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
Comment:	Shared meter run for Cope Nellie 1-16 and Federal 2-16X			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Churchill unit			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	Electric panel and cathodic rectifier			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	Open Top		37.342420,-102.391370	
Comment:	Fiberglass open top water tank. Tank is empty at time of inspection					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Berms have rodent burrows and need maintenance			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 07/24/2024

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	205623	Type:	WELL	API Number:	009-06034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Cope, Nellie 1-16 & Federal 2-16X)								
Corrective Action:	Submit production reports from previous 6 months							Date:	07/24/2024
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403836020	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6601334">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6601334</a>
715200426	location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6601333">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6601333</a>