

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2024

Submitted Date:

07/02/2024

Document Number:

717000004**FIELD INSPECTION FORM**Loc ID 320039 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202342	WELL	SI	03/01/2024	OW	001-07747	TRUPP 8-16	PR

**General Comment:**[Routine Inspection](#)

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment: Adequate					
Corrective Action:					
Date:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
					corrective date
Type: Pump Jack		# 1			
Comment:					
Corrective Action:					Date:
Type: Bird Protectors		# 1			
Comment:					
Corrective Action:					Date:
Type: Bradenhead		# 1			
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run		# 1			
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator		# 1			
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.796873,-104.454088
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-07747		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202342

Type: WELL

API Number: 001-07747

Status: SI

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/07/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

Routine inspection

finkenbc

07/02/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num

Description

URL

717000005

Inspection photos

<https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6609246>

Date Run: 7/2/2024 Doc [#717000004]

Page 4 of 4