

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2209 From entrance to location



Photo # 2210 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2211 Location



Photo # 2212 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2213 Location



Photo # 2214 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2215 Location



Photo # 2216 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2217 Location



Photo # 2218 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2219 Mechanical Condition – possible leak on chemical line connected to RWF 432-26 well casing valve



Photo # 2220 Mechanical Condition – possible leak on chemical line connected to RWF 432-26 well casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2221 Mechanical Condition – possible leak on chemical line connected to RWF 432-26 well casing valve



Photo # 2222 Mechanical Condition – possible leak on chemical line connected to RWF 432-26 well casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2223 Mechanical Condition – possible leak on chemical line connected to RWF 432-26 well casing valve



Photo # 2224 Mechanical Condition – possible leak on chemical line connected to RWF 432-26 well casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2225 Mechanical Condition – possible leak on bullplug connected to RWF 432-26 well casing valve



Photo # 2226 Mechanical Condition – possible leak on bullplug connected to RWF 432-26 well casing valve

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 32-26 Pad

Location ID: 335490



Photo # 2227 Mechanical Condition – possible leak on bullplug connected to RWF 432-26 well casing valve



Photo # 2228 Mechanical Condition – possible leaks on chemical line & bullplug connected to RWF 432-26 well casing valve