

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2024

Submitted Date:

07/03/2024

Document Number:

716200196**FIELD INSPECTION FORM**Loc ID 336361 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287004	WELL	PR	02/01/2024	GW	123-27335	RADEMACHER 24-30	PR

General Comment:

[Corrective action inspection.](#)
[Weed debris at wellhead and battery.](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Signage at wellhead refering to PA well.
Sign not posted or information inaccurate at well(s)

Corrective Action: Install sign to comply with Rule 605.d.

Date: 08/05/2024

Good Housekeeping:

Type DEBRIS

Comment: Weed debris at wellhead and battery.

Corrective Action: Comply with rule 606

Date: 08/05/2024

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type IGNITOR/COMBUSTOR

Comment:

Corrective Action:

Date:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		Shared with crude oil tanks.			
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.194500,-104.932380	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 287004 Type: WELL API Number: 123-27335 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test:	06/15/2023	Annual Brhd Completed?	
Last Brhd Test Results	Initial Surf Csg Pressure: 20	Fluid Type:	None
	End Surf Csg Pressure: --		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Corrective action inspection. Weed debris at wellhead and battery.	carlilec	07/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716200199	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6610606