

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Location Entrance – Photo #01909



West End of Location – Photo #01912

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Wellheads – Photo #01915



Separators – Photo #01911

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Heater Treater – Photo #01918



Tank Battery – Photo #01919

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Housekeeping/Debris – Photo #01920



Housekeeping/Debris – Photo #01921

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Open-Ended Load Line – Photo #01925



Sediment Run-Off from Location – Photo #01913

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Sediment Run-Off from Location – Photo #01914



Insufficient Erosion Control/Site Degradation – Photo #01928

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



Insufficient Erosion Control/Site Degradation – Photo #01926



Insufficient Erosion Control/Site Degradation – Photo #01927

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 6/27/2024



**Insufficient Erosion Control/Rill Erosion Bypassing Ditch
BMP on Access Road – Photo #01929**



**Insufficient Erosion Control/Rill Erosion Bypassing Ditch
BMP on Access Road – Photo #01931**