

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/03/2024

Submitted Date:

07/03/2024

Document Number:

715200466

FIELD INSPECTION FORM

Loc ID 321759 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

22 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| OBryhim, Reesa | | ROBryhim@mulldrilling.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 207936 | WELL | PR | 09/01/2022 | GW | 017-06871 | NW ARAPAHOE UT 15 | PR |

General Comment:

[Routine Inspection](#)

Location

| | | | |
|--------------------|--------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Elevated gravel road through pasture | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|----------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Stickers on chemical tanks | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal signs by tanks | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Lease sign by tank battery | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|--|
| Emergency Contact Number: | | | |
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Tank battery 3/4 fenced with wire | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|-------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run on east side of vent tank | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|--|--|-------|
| Type: Vertical Separator | # 2 | | |
| Comment: | 2-Vertical gas separators in metal shed on west side of vent tank | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | ECD on west side of oil tanks | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 4 | | |
| Comment: | Electric panel, cathodic rectifier, telemetry equipment at meter shed, elec circ pump by oil tanks | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heater Treater | # 1 | | |
| Comment: | Treater with metal shed on west side of horizontal treater | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | Parkersburg 160 | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heater Treater | # 1 | | |
| Comment: | Treater on west side of water tank | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Separator | # 1 | | |
| Comment: | HGS in metal shed with VGS | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 38.871910,-102.143590 |
| Comment: | Vent tank is on northeast corner of location | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|----------|--|---------------------|-------------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLs | Open Top | | 38.871660,-102.143590 |
| Comment: | | Fiberglass open top water tank on east side of HGS | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 38.871600,-102.144170 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | PVC lined steel containment | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Inspected Facilities

Facility ID: 207936 Type: WELL API Number: 017-06871 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(NWAU 14,15,16,17,19,27&28\) 480' S @ 38.87160/-102.144170](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | Material Handling And Spill Prevention | Pass | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 715200470 | location photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6611767 |
| 715200471 | NWAU 4 tank battery | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6611768 |