

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2024

Submitted Date:

06/27/2024

Document Number:

696306477**FIELD INSPECTION FORM**Loc ID 413543 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297454	WELL	TA	03/03/2019	OW	123-27148	ANTELOPE 41-19	TA
412531	WELL	TA	09/01/2019	OW	123-30509	ANTELOPE 42-19	TA
420770	WELL	TA	03/03/2019	OW	123-32712	Antelope 19G	TA
427851	WELL	TA	03/03/2019	OW	123-35126	Antelope P-19	TA
427853	WELL	TA	03/03/2019	OW	123-35128	Antelope W-19	TA
427856	WELL	TA	02/22/2019	OW	123-35130	Antelope R-19	TA
427863	WELL	TA	02/23/2019	OW	123-35135	Antelope X-19	TA

General Comment:

This is a Well PAD Inspection ONLY

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	X-19 (123-35135) - Faded no longer visible R-19 (123-35130) - Faded no longer visible W-19 (123-35128) - Faded no longer visible 19G (123-32712) - This Well Currently has the WRONG Well Sign on (42-19) on Wellhead 19G Wellhead Sign is missing		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/26/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Other	# 7		
Comment:	TA Wellheads		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297454 Type: WELL API Number: 123-27148 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Since 03.03.2019. MIT 03.26.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412531 Type: WELL API Number: 123-30509 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Since 09.01.2019. MIT 02.24.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 420770 Type: WELL API Number: 123-32712 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Since 03.03.2019. MIT 11.10.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427851 Type: WELL API Number: 123-35126 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Since 03.03.2019. MIT 02.11.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427853 Type: WELL API Number: 123-35128 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - Since 03.03.2019. MIT 02.11.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427856 Type: WELL API Number: 123-35130 Status: TA Insp. Status: TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Since 02.22.2019. MIT 03.26.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:

427863

Type:

WELL

API Number:

123-35135

Status:

TA

Insp. Status:

TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Since 02.23.2019. MIT 03.26.2021
Form 6A 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection. Wellhead Signs	petrie	06/27/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403838947	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604409
696306478	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604404