

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601181

FIELD INSPECTION FORM

Loc ID 321229 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
BEAR STACY L		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206379	WELL	PR	08/01/2018	GW	011-06126	HOFFMAN, EARL 1	RI

General Comment:

This is a follow up of the previous reclamation inspection #713600502, #713600769.
The previous inspection corrective actions were not completed.
Non-compliance with the Rules will be referred to enforcement.
See attached photos and additional details within this report.

Note: Documentation (FIRR) showing completion of corrective actions is requested within 2 weeks.
Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	The sign is faded and does not meet the requirements. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/27/2024

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment: <input style="width: 800px; height: 20px;" type="text"/>					
Corrective Action:					Date:

Paint

Condition	<input style="width: 150px; height: 20px;" type="text"/>
Other (Content)	<input style="width: 800px; height: 20px;" type="text"/>
Other (Capacity)	<input style="width: 800px; height: 20px;" type="text"/>
Other (Type)	<input style="width: 800px; height: 20px;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: The secondary containment is insufficient to contain a spill. Previous corrective action was not completed.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 06/27/2024

Venting:

Yes/No	<input style="width: 150px; height: 20px;" type="text"/>
Comment:	<input style="width: 800px; height: 20px;" type="text"/>
Corrective Action:	Date: <input style="width: 100px; height: 20px;" type="text"/>

Flaring:

Type	<input style="width: 150px; height: 20px;" type="text"/>
Comment:	<input style="width: 800px; height: 20px;" type="text"/>
Corrective Action:	Date: <input style="width: 100px; height: 20px;" type="text"/>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403838234	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603814
713601182	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6603812