

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601194

FIELD INSPECTION FORM

Loc ID 314203 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|-------------------------------|---------|
| Sanchez, Chris | | chris.sanchez@state.co.us | |
| STACY L BEAR | | stacy@strachanexploration.com | |
| Jordan LaPlante | | jordan_laplante@fws.gov | |
| Harms, Jason | | Jason@strachanexploration.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------------|--------|-------------|------------|---------|----------------|-------------|
| 444661 | GAS COMPRESSOR STATION | SI | 12/21/2016 | | - | NEU Compressor | RI |

General Comment:

This is a follow up of the previous inspection #713600839 at the NEU Compressor. The corrective actions of the previous inspection have not been completed. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|--|
| Type | BATTERY | | |
| Comment: | Tank battery sign and labels are missing and faded. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|--|
| Type | OTHER | | |
| Comment: | The migratory bird nest has been removed from the top of the tank. It is unknown if the Operator consulted with CPW and USFWS. A follow up will be determined. | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|--------------------|--|--------|--|-------|--|
| Condensate | Tank | | | | |
| Comment: | Previous inspection observed a leak at the tank that spilled E&P waste within the tank secondary containment. The spill has not been cleaned up since the previous inspection. Due to the amount spilled and no clean up performed, the Operator will need to submit a form 19 spill report to ensure proper clean up. | | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste and contact EPS staff per Rule 912.b. 72 hours for Initial Form 19 Report | | | Date: | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403839384 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604884 |
| 713601195 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604877 |

