

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2024

Submitted Date:

06/28/2024

Document Number:

696306495**FIELD INSPECTION FORM**Loc ID 418233 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418230	WELL	TA	12/14/2018	GW	123-31859	Antelope 21-19	TA
420897	WELL	TA	12/19/2018	OW	123-32737	Antelope 31-19	TA
427849	WELL	TA	12/19/2018	OW	123-35125	Antelope L-19	TA
427852	WELL	TA	12/31/2018	OW	123-35127	Antelope K-19	TA
427858	WELL	TA	08/01/2019	OW	123-35132	Antelope F-19	TA
427860	WELL	TA	03/21/2019	OW	123-35133	Antelope B-19	TA

General Comment:

This is a Well PAD Inspection ONLY

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	L-19 (123-35125), 31-19 (123-32737) and K-19 (123-35127) Wellhead Signs have faded no longer visible.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/29/2024

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:		
Type	STORAGE OF SUPL	
Comment:	Unused Automation Equipment and Batteries at Wellsite; see photos	
Corrective Action:	Comply with Rule 606	Date: 07/29/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Panels	
Corrective Action:		Date:

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	TA Wellheads		
Corrective Action:		Date:	

Venting:		
Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 418230 Type: WELL API Number: 123-31859 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA - Since 12.14.2018
MIT - 11.04.2020
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 420897 Type: WELL API Number: 123-32737 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA - Since 12.19.2018
MIT - 11.03.2020
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427849 Type: WELL API Number: 123-35125 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA - Since 12.19.2018
MIT - 10.06.2020
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427852 Type: WELL API Number: 123-35127 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA - Since 12.31.2018
MIT - 10.06.2020
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 on File

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427858 Type: WELL API Number: 123-35132 Status: TA Insp. Status: TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Well appears to have been Plugged and Abandoned per Form 42 PA - 403823432 with a MIRU date of 06.19.2024.
Form 6N - 403754080 on File
Not yet Cut and Capped
No Form 6S on File yet

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	427860	Type:	WELL	API Number:	123-35133	Status:	TA	Insp. Status:	TA
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Well appears to have been Plugged and Abandoned per Form 6S - 403717702 (In Process) dated 04.26.2024 with a Surface Plug date of 02.27.2024 and a Cut and Cap date of 04.08.2024

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection. Wellhead Signs and Unused Automation Equipment and Batteries	petrie	06/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403840358	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606090
696306496	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6606076