

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2024

Submitted Date:

06/27/2024

Document Number:

699505996

**FIELD INSPECTION FORM**

Loc ID 320225 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 31257  
Name of Operator: FRITZLER RESOURCES INC  
Address: P O BOX 114  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 12 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
,		gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	TA

**General Comment:**

There have been no changes to equipment on location since previous inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Pit appears to be closed on location, provide form 27, no form 27 on file. Pit was observed on previous inspections.		
Corrective Action:	Comply with rule 911 a	Date:	<u>06/06/2024</u>
Type	OTHER		
Comment:	Tanks sign is inadequate		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	<u>06/27/2024</u>
Type	OTHER		
Comment:	wellhead sign inadequate		
Corrective Action:	Comply with rule 605 d.	Date:	<u>06/06/2024</u>
Type	OTHER		
Comment:	Anchors are not marked with highly visible markers.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	<u>06/27/2024</u>
Type	OTHER		
Comment:	Lease road is not maintained.		
Corrective Action:	Comply with rule 204	Date:	<u>06/06/2024</u>
Type	OTHER		
Comment:	stormwater damage on south end of location by wellhead		
Corrective Action:	Comply with rule 1002.f.(2)C	Date:	<u>06/06/2024</u>
Type	OTHER		
Comment:	Berms inadequate around tank		
Corrective Action:	Comply with rule 603 o.	Date:	<u>06/06/2024</u>
Type	OTHER		
Comment:	Weeds unmanaged on locaion		
Corrective Action:	Comply with rule 606	Date:	<u>06/06/2024</u>
Type	OTHER		
Comment:	OOSLOT risers not tagged		
Corrective Action:	Comply with rule 1105	Date:	<u>06/06/2024</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203117 Type: WELL API Number: 001-08525 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On 6/26/24 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Linnebur 24-1                      Company Name- Fritzler resources INC                      API- 05-001-08525                      In AdamsCounty Colorado.                      While there, I observed TA well                      This is a follow up inspection from document # 699505911 Corrective Actions are Delinquent                      During this inspection the following possible compliance issues were observed:                      Pit closed no form 27. Rule 911 a. 6/6/24                      OOSLOT LOTO. Rule 1105. 6/6/24                      wellhead sign. Rule 605 d. 6/6/24                      stormwater. Rule 1002.f(2)C. 6/6/24                      Berms. Rule 603 o. 6/6/24                      Weeds. Rule 606. 6/6/24                      Access. Rule 204. 6/6/24                      Tank sign. Rule 605 a. 6/27/24                      Deadmen anchors. Rule 1003. A. 6/27/24                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	medinaj	06/27/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403839918	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605545">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605545</a>
699505997	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605542">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605542</a>