

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403798165

Date Received:
05/21/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: 501 N DIVISION BLVD
City: PLATTEVILLE State: CO Zip: 80651

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|---------------------|-------|---------------------------------|
| <u>Stormo, Drew</u> | | <u>drew_stormo@oxy.com</u> |
| <u>Lee, Austin</u> | | <u>austin_lee@oxy.com</u> |
| <u>-</u> | | <u>COGCCInspections@Oxy.com</u> |

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900603
Inspection Date: 05/07/2024 FIR Submit Date: 05/16/2024 FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 336371

Location Name: NESG-63N68W Number: 24SWSW County: _____
Qtrqr: SWS Sec: 24 Twp: 3N Range: 68W Meridian: 6
W
Latitude: 40.207520 Longitude: -104.957630

FACILITY - API Number: 05-123-00 Facility ID: 336371

Facility Name: NESG-63N68W Number: 24SWSW
Qtrqr: SWS Sec: 24 Twp: 3N Range: 68W Meridian: 6
W
Latitude: 40.207520 Longitude: -104.957630

CORRECTIVE ACTIONS:

1 CA# 195245

Corrective Action: Comply with the reclamation rules to remove all debris, abandoned gathering line risers, and flowline risers, and equipment (regardless of ownership) within three months of plugging (9/30/2021) the associated facility. All work should have been conducted by 12/30/2021.

Date: 06/16/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: Operator reached out to Western Midstream to determine whether the equipment was abandoned or active. Western Midstream said the riser was tied to active gathering lines and are currently in use.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please route to area reclamation specialist, operator reached out to midstream company who acknowledged that risers are tied to active lines and remain in use.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Drew Stormo Signed: _____

Title: Advisor HSE Environ Ops Date: 5/21/2024 9:33:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
| 403798165 | FIR RESOLUTION SUBMITTED |

Total Attach: 1 Files