

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2487 From entrance to location

Photo # 2488 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2489 Location



Photo # 2490 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2491 Location



Photo # 2492 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2493 Location



Photo # 2494 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2495 Location



Photo # 2496 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2497 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 2498 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



**Photo # 2499 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



Photo # 2500 Weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2501 Staining in secondary containment near frost free valve



Photo # 2502 Staining near wellhead

Inspection Photos

Location Name: CAERUS PICEANCE LLC EM 30-7 (B30NE) Pad

Location #: 335454



Photo # 2503 Staining near wellhead