



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/27/2024

Submitted Date:
07/01/2024

Document Number:
708904140

FIELD INSPECTION FORM

Loc ID
334848

Inspector Name:
Smelser, Wayne

On-Site Inspection ☐

2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

40 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210913	WELL	PR	09/07/1998	CBM	045-06671	FEDERAL 0-4-7-94-W	PR
297147	WELL	PR	06/30/2010	GW	045-16322	FEDERAL RWF 334-4	PR
297148	WELL	PR	06/30/2010	GW	045-16323	FEDERAL RWF 34-4	PR
297149	WELL	PR	06/30/2010	GW	045-16324	FEDERAL RWF 543-4	PR
297150	WELL	PR	06/30/2010	GW	045-16325	FEDERAL RWF 333-4	PR
297151	WELL	PR	07/31/2010	GW	045-16326	FEDERAL RWF 33-4	PR
297152	WELL	PR	06/30/2010	GW	045-16327	FEDERAL RWF 43-4	PR
297153	WELL	PR	06/30/2010	GW	045-16328	FEDERAL RWF 544-4	PR
297154	WELL	PR	06/30/2010	GW	045-16329	FEDERAL RWF 444-4	PR
297155	WELL	PR	06/30/2010	GW	045-16330	FEDERAL RWF 344-4	PR
297156	WELL	PR	05/16/2011	GW	045-16331	FEDERAL RWF 44-4	PR
297157	WELL	PR	06/30/2010	GW	045-16332	FEDERAL RWF 533-4	PR
297158	WELL	PR	06/30/2010	GW	045-16333	FEDERAL RWF 433-4	PR
297159	WELL	PR	06/30/2010	GW	045-16334	FEDERAL RWF 443-4	PR
297160	WELL	PR	06/30/2010	GW	045-16335	FEDERAL RWF 343-4	PR

General Comment:

Date Run: 7/8/2024 Doc [#708904140]

Page 1 of 9

CECMC Inspection Report Summary

On 06/27/2024 at approximately 12:38 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL0-4-7-94-W Pad.

Location # 334848 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 255 yards from Spruce Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Chemical tank label weathered/faded & some required info is illegible with a CA date of 07/31/2024
2. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 07/08/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Chemical tank label weathered/faded & some required info is illegible - please refer to photo log		
Corrective Action:	Comply with CECMC labeling rules	Date:	07/31/2024

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Small amount of staining near some wellheads		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/>	Multiple Spills and Releases?			

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks, liquid nitrogen tank & flameless gas infrared catalytic heater - hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	PRV vent line on tank burner does not comply with CECMC pressure safety device rules - please refer to photo log		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	07/08/2024
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 15		
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	HEATED STEEL AST		,	
Comment:	Tank equipped with telemetry					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	210913	Type:	WELL	API Number: 045-06671	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297147	Type:	WELL	API Number: 045-16322	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297148	Type:	WELL	API Number: 045-16323	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297149	Type:	WELL	API Number: 045-16324	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297150	Type:	WELL	API Number: 045-16325	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297151	Type:	WELL	API Number: 045-16326	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297152	Type:	WELL	API Number: 045-16327	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	297153	Type:	WELL	API Number: 045-16328	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297154	Type:	WELL
API Number:	045-16329	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297155	Type:	WELL
API Number:	045-16330	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297156	Type:	WELL
API Number:	045-16331	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297157	Type:	WELL
API Number:	045-16332	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297158	Type:	WELL
API Number:	045-16333	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297159	Type:	WELL
API Number:	045-16334	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	297160	Type:	WELL
API Number:	045-16335	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank containments
		Gravel				Sparse to none
		Ditches				
		Compaction				
Compaction						Light compaction in areas
		Culverts				
Gravel						Sparse to none in areas
Berms						
		Retention Ponds				
		Ditches				

Comment: Some signs of erosion developing in areas along fill slope (North side of location)
Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker & Equipment for corrective actions & also refer to Housekeeping & Stormwater for comments.	smelserw	07/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403841349	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607798
708904141	Inspection 708904140 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607795
708904142	Inspection 708904140 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607796