

From: Shad Brown <shbrown@hilcorp.com>

Sent: Monday, July 8, 2024 8:14 AM

To: Tammy Jones <tajones@hilcorp.com>; Francisco Enriquez Quintana <Francisco.Quintana@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Jennifer Street <jstreet@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>

Subject: RE: ARGENTA 34-10-33 3 - INC - 714000826

Storm water: Inspection doc #693904585 observed storm water issues in the northern portion of the disturbance and required compliance by 7/16/2022. It was observed in this inspection that storm water issues are persisting with gully erosion forming down slope of round river rock check dam, current storm water BMPs appear inadequate. Original CA has not been addressed. Original CA and date remains applicable. No CA date is being provided as this location is out of compliance for the same Rule.

Storm water issues have been addressed.

Impacted Surface Material: Impacted surface material observed at the pump jack and well head.

Impacted soil has been removed and disposed of properly.

Unused Equipment/Debris: Unused oil and gas piping and metal panels/debris observed on location.

Unused equipment and debris have been removed and disposed of properly.



Shad Brown

Area 1

505-609-3449

505-634-8207







