

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403843465

Date Received:

07/08/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 51130  
Name of Operator: LOCIN OIL CORPORATION  
Address: 600 TRAVIS STREET SUITE 5050  
City: HOUSTON State: TX Zip: 77002

#### Contact Name and Telephone:

Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name	Phone	Email
Tyler Faldyn	832-748-1090	tfaldyn@americanhelium.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 696205063  
Inspection Date: 06/21/2023 FIR Submit Date: 06/26/2023 FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130  
Address: 600 TRAVIS ST STE 6161  
City: HOUSTON State: TX Zip: 77002

#### LOCATION - Location ID: 322447

Location Name: FEDERAL-67S104W Number: 34SESW County: \_\_\_\_\_  
Qtrqtr: SESW Sec: 34 Twp: 7S Range: 104W Meridian: 6  
Latitude: 39.407364 Longitude: -108.978502

#### FACILITY - API Number: 05-045- -00 Facility ID: 322447

Facility Name: FEDERAL-67S104W Number: 34SESW  
Qtrqtr: SESW Sec: 34 Twp: 7S Range: 104W Meridian: 6  
Latitude: 39.407364 Longitude: -108.978502

### CORRECTIVE ACTIONS:

1 CA# 173879

Corrective Action: Install or Maintain BMP to ensure containment is sufficiently impervious to contain spill or release.

Date: 05/04/2023

Response: CA COMPLETED Date of Completion: 07/05/2024

Operator Comment: Well has been plugged and abandoned 05/04/2023, Form 6 Doc #403621878

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 173880

Corrective Action: Clean/remediate stained soils on Location to Table 915-1 standards.

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator  
Comment: Stained soil removed.

ECMC Decision:

ECMC  
Representative:

3 CA# 173881

Corrective Action: Comply with Rule 605.h

Date: 05/04/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator  
Comment: Tanks were removed when plugging and abandonment of well occurred. No signage for tanks remains.

ECMC Decision:

ECMC  
Representative:

4 CA# 173882

Corrective Action: Comply with Rule 605.d

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator  
Comment: Signage updated to comply with Rule 605.h for location.

ECMC Decision:

ECMC  
Representative:

5 CA# 173883

Corrective Action: Properly cap exposed lines and comply with OOSLAT requirements.

Date: 04/07/2023

Response: CA COMPLETED

Date of Completion: 07/06/2024

Operator  
Comment: Lines are capped. Please see attached photo.

ECMC Decision:

ECMC  
Representative:

6 CA# 173884

Corrective Action: Comply with Rule 605.e

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Tank battery was removed when well was plugged and abandoned.

---

7	CA# 173885
---	------------

Comply with Rule 605.h

Date: 05/04/2023

CA COMPLETED

Date of Completion: 07/05/2024

Tanks were removed when plugging and abandonment occurred. No required tank signage remains.

\_\_\_\_\_

8 CA# 174461

Comply with Warning Letter doc#403160055 issued 9/9/2022.

Date:

CA COMPLETED

Date of Completion: 07/05/2024

Well has been plugged and abandoned. Additional corrective actions are being completed to correct the record.

OPERATOR COMMENT AND SUBMITTAL
--------------------------------

Well was plugged and abandoned May 4th, 2023. Dates for the corrective actions are last Friday as that is when the photos were taken, but the actions were completed some time before.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Niah Wilson

Signed:

Regulatory Specialist

Date: 7/8/2024 2:28:03 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403847000	Well site P&A'd
403847003	Flowlines capped
403847004	Soil
403847006	Sign at wellhead
403847197	6S Document Returned to Draft

Total Attach: 5 Files