

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2024

Submitted Date:

07/08/2024

Document Number:

697009684**FIELD INSPECTION FORM**Loc ID 305743 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281692	WELL	SI	07/01/2021	OW	123-23419	JEFFERS 12-35	TA

General Comment:

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator personnel on location at the time of this field inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Operator information is illegible, see attached photo.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	08/09/2024

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds are growing throughout location, see attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	08/09/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Chain link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Flow Line	# 1		corrective date
Comment:	OOSLAT		
Corrective Action:		Date:	

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	TD'd		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Automation array and two ECD scrubbers		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,	
Comment:	48 bbls					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date: <div></div>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <div></div>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <div></div>

Inspected Facilities									
Facility ID:	281692	Type:	WELL	API Number:	123-23419	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: Form 6A #403108165									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 01/16/2024									
Annual Brhd Completed? Yes									
Last Brhd Test Results									
Initial Surf Csg Pressure: 0									
Fluid Type: None									
End Surf Csg Pressure: --									
Comment:									
Corrective Action:									
Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Pass			

Comment: [Location has sustained heavy erosion damage, see attached photos.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 08/09/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
COGCC Inspection Report Summary On Monday 7/8/2024 at approximately 11:30 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KMG Jeffers 12-35 location #305743 in Weld County, Colorado. While there, I observed that the battery sign producer decal required replacement, weeds were growing throughout the location, and the battery had sustained heavy erosion damage. During this inspection the following possible compliance issues were observed: Rule 605.e. with a corrective action date of 8/9/2024, Rule 606. with a corrective action date of 8/9/2024, Rule 1002.f.(2)C. with a corrective action date of 8/9/2024. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.	petersont	07/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697009685	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6614992