

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2024

Submitted Date:

07/08/2024

Document Number:

705000745**FIELD INSPECTION FORM**Loc ID 330295 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251015	WELL	SI	01/01/2021	GW	123-18818	HSR-DAVIS, V 5-26A	PA
330295	LOCATION	AC			-	HSR-DAVIS, V-63N67W 26SWNW	EG

**General Comment:**

ECMC Engineering Integrity Inspection; Flowline Inspection

Photos uploaded

Inspected Facilities									
Facility ID:	251015	Type:	WELL	API Number:	123-18818	Status:	SI	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	330295	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
Well is plugged and abandoned (HSR Davis 5-26A); ECMC form 42 notice of start of plugging operations doc #403617396 received on 12/07/2023. The OLF is AIP; ECMC form 42 notice of flowline abandonment completed doc #403715419 received 03/11/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed. No flowlines/ risers observed at PA well or facility/ battery areas. Excavation and remediation work is in progress.	maclarej	07/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000748	Fenced excavations at facility; signage	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6614996">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6614996</a>
705000749	View of location to S; OOS GMR	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6614997">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6614997</a>