

Construction and Stormwater Inspection

Date: 06/25/2024

Operator: PDC ENERGY INC - 69175

Location ID: 453934

Inspection Document #: 708201357

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 1. Taken near the location entrance. Undesirable vegetation (e.g. field bindweed, poison hemlock, scotch thistle, smooth broome, curly dock, cheatgrass, etc) observed.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 2. Continued from Photo 1, facing north.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 3. Trash and debris observed near the location entrance.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 4. Continued from Photo 3.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934




Photo 5. Stained soil observed at AST.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 6. Eight (8) additional wells have been drilled at the location.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 7. East side of location. Undesirable vegetation and trash/debris observed throughout the perimeter of the location. Red arrow indicating buried pipe.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 8. East side of location; see comments in Photo 7.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 9. East side of location; see comments in Photo 7.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 10. Northeast corner of location; see comments in Photo 7.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 11. North side of location; see comments in Photo 7.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 12. West side of location; see comments in Photo 7.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 13. Topsoil stockpile appears to have been recently mowed. However, the predominant vegetation cover appears to be kochia and curly dock. Additional revegetation activities are required to comply with Rule 1002.c.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 14. Facing south; see comments in Photo 13.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 15. Southwest corner of the location; see comments in Photo 7.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 16. South side of location. Crews were actively managing the undesirable vegetation at the time of this inspection.

Inspection Photos
Location Name: Edmundson #30
Location ID: 453934



Photo 17. Southeast corner of the location; see comments in Photo 16.