



**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Adequate		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 243370 Type: WELL API Number: 123-11161 Status: SI Insp. Status: SI

**BradenHead**

Date of Last Brhd Test: 06/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 35 Fluid Type: GAS

End Surf Csg Pressure: 1

Comment: Plumbed to surface.

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment: WO Rig crew TOO H pulling the packer setting stands in the derrick preparing for Wireline logs.

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">This Field Inspection is due to a Form 42 (MIRU)-00 Doc # 40383959 &amp; 42 (PA)-00 Doc # 403836976.</a> Weather: Clear & hot Location: Dry	revasr	07/08/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716400256	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6615247">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6615247</a>