

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2024

Submitted Date:

07/02/2024

Document Number:

697009674**FIELD INSPECTION FORM**Loc ID 439811 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**24 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439810	WELL	PR	01/01/2020	OW	123-40565	Rieder 18T-321	PR
439812	WELL	TA	05/31/2023	OW	123-40566	Rieder 18Y-301	TA
439813	WELL	PR	03/01/2018	OW	123-40567	Rieder 18Y-241	PR
439814	WELL	PR	10/17/2015	OW	123-40568	Rieder 18T-401	PR
439815	WELL	TA	06/07/2023	OW	123-40569	Rieder 18T-221	TA
439816	WELL	PR	10/12/2015	OW	123-40570	Rieder 18Y-441	PR

General Comment:

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator personnel on location at the time of this field inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol systems		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 6		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	East soundwall metal panels have been damaged and are on the ground and alfafa field, see attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	08/09/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Panel x 5		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel x 6		
Corrective Action:		Date:	
Type	OTHER		

Comment: Soundwalls at compressors			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Emission Control Device	# 5		
Comment: Pilots are on			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment: Automation array, solar array, ECD scrubbers, methanol systems in secondary containment, bulk lube oil storage in secondary containment with wildlife protection.			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 3		
Comment: Natural gas engines on compressors and VRU.			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment: Bradenhead valves are exposed at surface.			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: DCP calibration card is current			
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment: 210 bbls						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Lined berm					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	OTHER	STEEL AST		,	
Comment: 538 bbls						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Lined berm					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 439810 Type: WELL API Number: 123-40565 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 44 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439812 Type: WELL API Number: 123-40566 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Form 21 #403418034

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/04/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 25 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439813 Type: WELL API Number: 123-40567 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 78 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439814 Type: WELL API Number: 123-40568 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test:	07/04/2023	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439815 Type: WELL API Number: 123-40569 Status: TA Insp. Status: TA

Idle Well			
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder:
Comment:	Form 21 #403426451		
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test:	01/16/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 50	Fluid Type:	WATER AND GAS
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439816 Type: WELL API Number: 123-40570 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test:	07/04/2023	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 8	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 7/2/2024 at approximately 12:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Reider 4N67W 18Y Pad location #439811 in Weld County, Colorado.</p> <p>While there, I observed trash on location. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 8/9/2024. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	07/02/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403843710	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6609913
697009675	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6609911