

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403843465

Date Received:
07/08/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tyler Faldyn</u>	<u>832-748-1090</u>	<u>tfaldyn@americanhelium.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205063
Inspection Date: 06/21/2023 FIR Submit Date: 06/26/2023 FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 322447

Location Name: FEDERAL-67S104W Number: 34SESW County: _____
Qtrqtr: SESW Sec: 34 Twp: 7S Range: 104W Meridian: 6
Latitude: 39.407364 Longitude: -108.978502

FACILITY - API Number: 05-045-00 Facility ID: 322447

Facility Name: FEDERAL-67S104W Number: 34SESW
Qtrqtr: SESW Sec: 34 Twp: 7S Range: 104W Meridian: 6
Latitude: 39.407364 Longitude: -108.978502

CORRECTIVE ACTIONS:

1 CA# 173879

Corrective Action: Install or Maintain BMP to ensure containment is sufficiently impervious to contain spill or release. Date: 05/04/2023

Response: CA COMPLETED Date of Completion: 07/05/2024

Operator Comment: Well has been plugged and abandoned 05/04/2023, Form 6 Doc #403621878

ECMC Decision: Approved

Per photo documentation equipment has been removed.

ECMC
Representative:

2 CA# 173880

Corrective Action: Clean/remediate stained soils on Location to Table 915-1 standards.

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator
Comment: Stained soil removed.

ECMC Decision: Approved pending re-inspection

ECMC
Representative: A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 CA# 173881

Corrective Action: Comply with Rule 605.h

Date: 05/04/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator
Comment: Tanks were removed when plugging and abandonment of well occurred. No signage for tanks remains.

ECMC Decision: Approved

ECMC
Representative: Per photo documentation equipment has been removed.

4 CA# 173882

Corrective Action: Comply with Rule 605.d

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator
Comment: Signage updated to comply with Rule 605.h for location.

ECMC Decision: Approved

ECMC
Representative: Per photo documentation signage was installed at well.

5 CA# 173883

Corrective Action: Properly cap exposed lines and comply with OOSLAT requirements.

Date: 04/07/2023

Response: CA COMPLETED

Date of Completion: 07/06/2024

Operator
Comment: Lines are capped. Please see attached photo.

ECMC Decision: Approved

ECMC
Representative: Per photo documentation equipment has been capped.
Pursuant to Rule 1004.a, all surface equipment is required to be removed within 90 days of plugging.

6 CA# 173884

Corrective Action: Comply with Rule 605.e

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator Comment: Tank battery was removed when well was plugged and abandoned.

ECMC Decision: Approved

ECMC Representative: Per photo documentation equipment has been removed.

7 CA# 173885

Corrective Action: Comply with Rule 605.h

Date: 05/04/2023

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator Comment: Tanks were removed when plugging and abandonment occurred. No required tank signage remains.

ECMC Decision: Approved

ECMC Representative: Per photo documentation equipment has been removed.

8 CA# 174461

Corrective Action: Comply with Warning Letter doc#403160055 issued 9/9/2022.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/05/2024

Operator Comment: Well has been plugged and abandoned. Additional corrective actions are being completed to correct the record.

ECMC Decision: Approved pending re-inspection

ECMC Representative: A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Well was plugged and abandoned May 4th, 2023. Dates for the corrective actions are last Friday as that is when the photos were taken, but the actions were completed some time before.

ECMC Reclamation Specialist Trujillo is adding the following comment to this resolution:
After submission of the FIRR, Operator emailed Reclamation Specialist with additional information Operator had wanted to include within the FIRR. Information per the Email below:

-Equipment was hauled off 8/1/23 by SRS. The lines were dug out and the wellhead cut and capped on 9/14/2023 & 9/22/2023.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Niah Wilson

Signed: _____

Title: Regulatory Specialist

Date: 7/8/2024 2:28:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403843465	FIR RESOLUTION SUBMITTED
403847000	Well site P&A'd
403847003	Flowlines capped

403847004	Soil
403847006	Sign at wellhead
403847197	6S Document Returned to Draft

Total Attach: 6 Files