

# Inspection Photos

07/08/2024

**Operator:** CHEVRON USA INC #16700

**Location ID:** 316610

**Inspection Doc:** 696205961

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 1:** Photos taken from the south end of the Location, facing northwest and northeast. Photos provide an overview of the Location; work pursuant to 1004.a including, but not limited to, recontouring/regrading, compaction alleviation, replacement of topsoil and reclamation has not been performed on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 2:** Photos 2-3 taken from the east end of the Location. Photos provide an overview from south, southwest, northwest to north. See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



July 8, 2024

**Photo 4:** Photo taken from the northeast end of the Location, facing west. Photo shows cut slopes remaining on the Location. Slopes are bare and erosion degradation is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



July 8, 2024

**Photo 5:** Photo taken from the north end of the Location, facing west. Photo shows what appears to be topsoil stockpiled above the cutslope. Topsoil on Location has not been replaced, is predominantly bare, and has not been protected pursuant to Rule 1002.c.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 6:** Photos taken from the north end of the Location, facing southeast and southwest. See comments under photo 1



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 7:** Photos examples showing Undesirable Plant Species (Mullein) have continued to spread and establish on the Location and access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 8:** Photos taken from the west end of the Location. Photos examples showing bare topsoil stockpiles on the Location. Photo also example showing location has not been recontoured/regraded and reclaimed in accordance with 1004 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 316610



**Photo 9:** Photos examples showing the access road has not been recontoured/regraded and reclaimed in accordance with Rule 1004.a.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 316610



**Photo 10:** 2023 Google Earth aerial image. Photo provides an aerial overview of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources