

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/09/2024

Document Number:

697009698**FIELD INSPECTION FORM**Loc ID 329899 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483367	WELL	DG	04/05/2024		123-51899	CAMENISCH 33-6HZ	DG
483368	WELL	DG	04/06/2024		123-51900	CAMENISCH 33-7HZ	DG
483369	WELL	DG	04/01/2024		123-51901	CAMENISCH 33-2HZ	DG
483370	WELL	DG	04/02/2024		123-51902	CAMENISCH 33-3HZ	DG
483372	WELL	DG	04/04/2024		123-51904	CAMENISCH 33-5HZ	DG
483374	WELL	DG	04/03/2024		123-51906	CAMENISCH 33-4HZ	DG

General Comment:

This is a drilling inspection.

Inspected FacilitiesFacility ID: 483367 Type: WELL API Number: 123-51899 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483368 Type: WELL API Number: 123-51900 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483369 Type: WELL API Number: 123-51901 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483370 Type: WELL API Number: 123-51902 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483372 Type: WELL API Number: 123-51904 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483374 Type: WELL API Number: 123-51906 Status: DG Insp. Status: DG**Well Drilling**Rig: Rig Name: Precision 562 Pusher/Rig Manager: James GoberPermit Posted: SATISFACTORY Access Sign: SATISFACTORY**Well Control Equipment:**Pipe Ram: YES Blind Ram: YES Hydril Type: YESPressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES**Drill Fluids****Management:**Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____Multi-Well: YES Disposal Location: Waste ConnectionsComment: Well has been TD'd @ 19,712' KB, crew is currently running casing.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Pass			
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697009699	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616431