

Inspection Photos on July 9th, 2024
Operator: Strachan Exploration
Location Name: Frazee-Bolyard 1-35
API: 05-061-06202



1. Overview of location



2. Stained soil at the wellhead
needs removed

Inspection #715200487

Inspection Photos on July 9th, 2024
Operator: Strachan Exploration
Location Name: Frazee-Bolyard 1-35
API: 05-061-06202



3. Southeast corner of tank battery looking north at spill outside of berms. There is some crude oil from the spill that traveled south in the adjacent cropland



4. Standing inside the berms looking north. Spill had breached the berms and went outside of containment

Inspection #715200487

Inspection Photos on July 9th, 2024
Operator: Strachan Exploration
Location Name: Frazee-Bolyard 1-35
API: 05-061-06202



5. There is a skim of oil from the mess being somewhat cleaned up by a vac truck



6. The spill appears to be from the overflow tank exceeding its capacity and spilling into the berms

Inspection #715200487

