

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/09/2024

Document Number:

715200487**FIELD INSPECTION FORM**Loc ID 324812 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Harms, Jason		jason@strachanexploration.com	
Reed, Shawn		shawn@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212842	WELL	PR	07/03/2017	OW	061-06202	FRAZEE-BOLYARD 1-35	PR

**General Comment:**

Routine Inspection

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign mounted to stairs		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels are faded and need replaced		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/09/2024

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	Tank	>= 5 bbls		
Comment:	Produced water has breached the berms and ran into adjacent farm land to the east (see photos). Operator has 30 days to remove stained soil and 24hrs to remove free fluid in accordance with 912.a			
Corrective Action:	Report spill or release of E&P waste or produced fluids. Remove free fluids and contact COGCC EPS staff per Rule 912.b. Recover free liquids and properly dispose in accordance with 905.c. Contact COGCC EPS staff regarding Rule 912.c.			Date: 07/10/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Alten 160		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	FWKO on south side of open top tank		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		38.367360,-102.313960

Comment: [Black water tank used as gun barrel](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Shared berms](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	Open Top		38.367360,-102.313960

Comment: [Fiberglass open top water tank](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Shared berms](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		38.367360,-102.313960

Comment: [3-Steel production tanks. The south tank has the manway cover removed and is rusted around the base.](#)Corrective Action: [Inspect, maintain and repair tanks to comply with rule 609.b.](#)Date: [08/09/2024](#)**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

Inspected Facilities									
Facility ID:	212842	Type:	WELL	API Number:	061-06202	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<a href="#">Report spills within 24hrs. Contact EPS for further directives</a>	welshb	07/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200488	location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616583">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616583</a>