

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

07/09/2024

Document Number:

709100329

FIELD INSPECTION FORMLoc ID 317320 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 81720

Name of Operator: STANDLEY* ROBERT K DBA OTIS ENERGY

Address: 315 SOUTH VINE STREET

City: OTIS State: CO Zip: 80743

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Ellen Standley		venture2.es@gmail.com	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
317320	LOCATION	AC			-	GEOGLEIN-62N49W 13SWSE	EI

General Comment:

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

On Wednesday June 26, 2023 an environmental inspection was performed for the GEOGLEIN 5 well and location.

Operator personnel was not present during time of inspection. Photos attached to document site conditions.

Operator Name: STANDLEY* ROBERT K DBA OTIS ENERGY

Location Name: GEOGLEIN-62N49W 13SWSE #1

API: 05-121-10574

Location ID: 317320

County: Washington County, Colorado

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment: Hydrocarbon impacted soils observed on location, near north side of pit.				
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.			Date:	06/26/2024

In Containment: No

Comment: ☒ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment: No equipment left on location. Evidence of facility abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC.			
Corrective Action: Operator shall submit a Site Investigation and Remediation Workplan (Form 27) detailing the plans to decommission this facility in accordance with the 900 series rules.		Date:	06/26/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment: Tank battery removed Evidence of facility abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC.						
Corrective Action: Operator shall submit a Site Investigation and Remediation Workplan (Form 27) detailing the plans to decommission this facility in accordance with the 900 series rules.				Date:	06/26/2024	

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	<input type="text"/>		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	317320	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment:

Vegetation growth on berms. Evidence of pit closure/abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC.

Corrective Action: Date: 06/26/2024

Operator shall submit a Site Investigation and Remediation Workplan (Form 27) detailing the plans to decommission this facility in accordance with the 900 series rules.

Netting:Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100330	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616575