

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

07/09/2024

Document Number:

709100337**FIELD INSPECTION FORM**Loc ID 317042 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 75000Name of Operator: BYRD\* CAROL W TRUSTEE OF CAROL W BYRDAddress: 8163 E 131 RDCity: WETUMKA State: OK Zip: 74883-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Carol Byrd		cwbyrd@oilandgasroyalties.com	
Krystal Heibel		krystal.heibel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234894	WELL	PR	12/05/1995	OW	121-07036	LYLE CHANDLER 1	EI
317042	LOCATION	AC			-	LYLE CHANDLER-62N49W 10NESE	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:				Date: _____	
Corrective Action:					
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
Crude Oil	WELLHEAD				
Comment:			Hydrocarbons observed leaking from wellhead and around polish rod.		
Corrective Action:			Control and contain spills/releases and clean up per Rule 912.a.		Date: 07/26/2024
Crude Oil	Pump Jack				
Comment:			Hydrocarbon impacted soils next to pumping unit.		
Corrective Action:			Control and contain spills/releases and clean up per Rule 912.a.		Date: 07/26/2024
In Containment: No					
Comment:					
<input checked="" type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
Type:		#			corrective date
Comment:		Wildlife protections devices not adequate around secondary containment.			
Corrective Action:		Install or repair wildlife protection equipment.			Date: 07/19/2024
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	234894	Type:	WELL	API Number:	121-07036	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	317042	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100338	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616579">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616579</a>