

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2024

Submitted Date:

07/09/2024

Document Number:

709100343

FIELD INSPECTION FORM

Loc ID 317278 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10690
Name of Operator: IMPETRO RESOURCES LLC
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Bongers, Brent	361-935-5633	bbongers@impetroresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237708	WELL	PR	08/01/2020	OW	121-10211	CHANDLER 2-15	EI

General Comment:

[This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
Comment: Hydrocarbon-stained soil observed around the wellhead.				
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.				Date: 07/26/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment: Wildlife protections devices not adequate for secondary containment around poly-tanks.			
Corrective Action: Install or repair wildlife protection equipment.			Date: 07/26/2024

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:			Date:

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 237708 Type: WELL API Number: 121-10211 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100344	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616582