

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Weeds**

**Weeds**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Oily waste from equipment leak**



**Stained soil**

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310



Debris



Illegible label

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310



**Illegible label. Broken equipment.**



**Tank cracked**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**When replaced additional information is required**



**Debris**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Weeds**

**Weeds**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Relief risers missing protective covers**




**Rain cap**

KT Resources LLC  
 Ant Hill Unit 19-44  
 Location ID: 316310



Weeds



Calibration overdue

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Location from Northwest corner**



**Location from Southwest corner**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Location from Southeast corner**



**Location from Northeast corner**